

FIG. 1




FIG. 1




FIG. 2

FOUO-242260




FIG. 3




FIG. 4




FIG. 5

7000-242000







FIG. 6



Conventional definition of zero Crossings. There are 4 zero Crossings.



Modified definition of zero crossings. For θ_1 there is one zero crossing and for θ_2 there are no zero crossings.

FIG. 7




FIG. 8

FORM 2-7-60




FIG. 9




FIG. 10




FIG. 12




FIG. 11